


**HEADLOSS CHART
1/4" THRU 3/4"
MODEL 816**

PRESSURE LOSS (psi)

PSI	FEET
10	23.1
8	18.5
6	13.9
5	11.5
4	9.2
3	6.9
2	4.6
1	2.3



FLOW RATE (gpm)